



500 Series Quick Start

Below is a very brief summary of the installation instructions. Refer to the **QSI 500 Series Camera Installation Guide** on the Installation CD, **Manuals\QSI Installation Guide.pdf**, for complete software and hardware installation instructions.

Vista Users - Note the special installation instructions in step 2 below and on the other side of this document.

Do not connect the camera to your computer until instructed to do so during the camera installation process

1. Insert the CD



Your QSI 500 Series camera comes with a CD containing the camera drivers and MaxIm LE. The USB camera drivers and associated software included on the installation CD **must** be installed before connecting your QSI camera to your computer.

- Login as a user with Administrator privileges
- Insert the Installation CD
- The Installer will launch automatically
- XP Users - If the installer doesn't start automatically, open the CD and double-click "Menu.exe" to launch the installer

2. Run the Installer



- **Vista Users – STOP**
See other side for special instructions

- Click "Install Products" to display the Installation menu
- Click "Install Camera Software" to install the QSI camera software and drivers. Follow the on-screen instructions
- If you haven't already opened the Installation Guide, do so now by clicking the Start button and select Programs > QSI > 500 Series Installation Guide
- The Installation Guide provides step-by-step instructions for completing the installation process and plugging in the QSI camera for the first time

3. Plug in the camera



- Plug the included power supply into the camera
- **Only** when instructed to do so in the QSI Camera Installation Guide, connect the camera to your computer using the included USB cable. Follow the on-screen instructions
- Install MaxIm LE and the MaxIm QSI Plug-in by clicking the appropriate options in the Installer window
- Or optionally, install the included camera Plug-In for your existing copy of MaxIm DL or CCDSoft
Note: Each installation of MaxIm or CCDSoft requires its own copy of the plug-in




500 Series Microsoft Vista Supplement

Vista has additional security measures to reduce the chances for drivers or software to be installed without your express permission. Please follow the instructions below to install your QSI camera drivers and software

Windows XP Users – STOP

This extra step is required only when running Vista. Follow standard instructions on the other side of this page.

2a. Provide Permission to Run each Installer



Each time a program is launched that requires Administrator privileges, Vista will display a "User Account Control" dialog box to confirm that you wish to run the program.

- Click Continue
- **NOTE: If User Account Control is enabled on your system, Vista will display a UAC dialog box multiple times during the installation process. Click Continue each time you see it**

***Turn page over and continue with
"2. Run the Installer"***